Release Notes

RoboSep™-S Software Version 1.5.3.

These release notes describe the new functionality and/or fixes to the previous RoboSep™-S Software Version 1.5.2.

Product Name/Description	Catalog #
RoboSep™-S	21000

Software	New Functionality/Fix
RoboSep™-S Software Version 1.5.3.	Bug Fixes • Resolved bugs affecting proper software startup • Updated Carousel path configuration • Corrected and decreased the gap between the 5 mL tip end and the buffer bottle bottom • Updated STEMCELL contact information in software logs • Improved log files used by service engineers for troubleshooting

NOTE: To apply RoboSep™-S Software Version 1.5.3, RoboSep™-S (Catalog #21000) must be currently running software version 1.5.2. If the instrument is running software 1.4.X or lower, please contact your sales representative or the service team or request the update during your next routine service appointment.

Copyright © 2026 by STEMCELL Technologies Inc. All rights reserved including graphics and images. STEMCELL Technologies & Design, STEMCELL Shield Design, Scientists Helping Scientists, and RoboSep are trademarks of STEMCELL Technologies Canada Inc. All other trademarks are the property of their respective holders. While STEMCELL has made all reasonable efforts to ensure that the information provided by STEMCELL and its suppliers is correct, it makes no warranties or representations as to the accuracy or completeness of such information.

UNLESS OTHERWISE STATED, PRODUCTS ARE FOR RESEARCH USE ONLY AND NOT INTENDED FOR HUMAN OR ANIMAL DIAGNOSTIC OR THERAPEUTIC USES. FOR PRODUCT-SPECIFIC COMPLIANCE AND INTENDED USE INFORMATION, REFER TO THE PRODUCT INFORMATION SHEET. GENERAL INFORMATION ON QUALITY AT STEMCELL MAY BE FOUND AT **WWW.STEMCELL.COM/COMPLIANCE.**